



A number of General Motors' high performance models come factory equipped with tires optimized for dry road perfor-

mance. As a result, the tread life characteristics of these tires may be reduced to achieve higher performance levels. Tread

life of high performance tires may be half that of a typical all-season tire, or less. Individual driving behavior will also affect ultimate wear performance. To prolong the life of these tires, tire rotation is recommended at 3,000 mile (4828 km) intervals.

TIP: Tires cannot be rotated if they are different sizes, front and rear. If unsure, check the owner's manual.

TIP: For 2005, performance tires are installed on Chevrolet Corvette and certain applications of Chevrolet Cobalt, Cadillac CTS and STS, and Pontiac Grand Prix.

Inflation pressure is very important and should be checked at least monthly. Tires should be checked cold, and should be adjusted to the pressure on the vehicle's tire placard, NOT the max pressure on the tire's sidewall.

Underinflation will increase tire wear, decrease fuel economy, and decrease load carrying capacity. Overinflation will result in a harsh ride. Either can adversely affect handling.

continued on page 2

Techline News

Tech 2 Pathing Tables

These handy Tech 2 quick reference Pathing Tables are now available on the TechLink website, under the Reference Guides tab. They will no longer be printed on cards.

You can use the Pathing Tables to quickly locate items such as data, input/output controls and service programming on your Tech 2. These tables are a must for anyone performing diagnostic procedures on current and future GM vehicles utilizing GM LAN and Class 2 protocols.

An important benefit of presenting the tables on the web is the ability to search. The contents are arranged

alphabetically, beginning with the end result – the final "string" displayed on the Tech 2 screen. There's an alphabet across the top of each page. Click on

continued on page 2

A B C D E F G H I J K L M N O P Q R S T U V W X Y Z

Tech 2 Pathing

Most of the practical Tech 2 pathing is listed on the following pages for your reference. Paths are arranged alphabetically beginning with the end result – the final "string" displayed on the Tech 2 screen.

Depending on the vehicle, each path aligns with one of 12 selections: **Powertrain, Chassis, Body, Vehicle Control Systems, HVAC, Steering, Suspension, Drives, Engine, Transmission/Transaxle, Body and Accessories, and Restraints**.

Search for a specific string by clicking one of the letters above to take you closer to the end string you seek, or by clicking on the Adobe Reader keyword "Find" icon  (usually located on the toolbar near the top of your screen) and typing in the exact phrase.

- 1.0-1.4 Drive Selection - Powertrain > Special Functions > Transmission Output Controls
- 1.0-1.4 Drive Selection - Powertrain > Special Functions > Transmission Output Controls > Select Control
- 1.0 Select - Powertrain > Special Functions > Transmission Output Controls
- 1.0 Select - Transmission/Transaxle > Automatic Transaxle > select optional capabilities if applicable > Special Functions > Powertrain Control Module
- 1.0 Select - Transmission/Transaxle > Automatic Transaxle > Special Functions > Transmission Control Module
- 1.4 Shift Lamp - Powertrain > Special Functions > Engine Output Controls > Dash-Lamps
- 1.4 Shift Select - Powertrain > Special Functions > Engine Output Controls
- 1.4.0.0 Command - Powertrain > Special Functions > HPCB Output Controls
- 1.4.1 - Body > Instrument Panel Cluster > Special Functions > PMSB, Shifter
- 2 Wheel Base Slide-Lamp - Chassis > Power Steering > Special Functions
- 2.0 Shift Select - Powertrain > Special Functions > Transmission Output Controls > Select Control
- 2.0 Select - Powertrain > Special Functions > Transmission Output Controls
- 2.0 Select - Transmission/Transaxle > Automatic Transaxle > select optional capabilities if applicable > Special Functions > Powertrain Control Module
- 2.0 Select - Transmission/Transaxle > Automatic Transaxle > Special Functions > Transmission Control Module
- 2.0.0 - Body > Instrument Panel Cluster > Special Functions > PMSB, Shifter
- 2nd Gear Shift Lamp - Powertrain > Special Functions > Transmission Output Controls
- 2nd High Intensity Light - Powertrain > Special Functions > HPCB Output Controls
- 3 Speed Fan - Powertrain > Special Functions > Engine Output Controls > Fan Controls
- 3.0 Transaxle Select - Powertrain > Special Functions > Transmission Output Controls

[Go to next page](#) [Return to top](#) 2005 Tech-2 Pathing 1

Contents

Performance Tires	.1
Tech 2 Pathing Tables	.1
Corvette Service Notes	.2
Windnoise Diagnosis Guide for SSR	.3
Memory Seat Module	.3
Keyless Entry Key Fob Verification	.3
Caster Measurement	.3
Oil Life System Reset -- Cars	.4
Wiring Harness Repair Issues	.6
New Model Features on the Web	.6
Front Drive Axle Lubricant	.7
Tie Rod Specifications Revised	.7
Headlamps On in Daytime	.7
Battery Draw	.7
Intermittent Dome Lamp Operation	.7
Interior Turning Pink	.7
Fix It Right the First Time	.8
Know How Broadcasts for October	.8

Performance Tires — from page 1

TIP: If a vehicle has been parked for some time, the tires may develop a temporary flat spot. This may result in a vibration until the tires are warmed up, which may take up to 10 miles of driving.

GM has developed and matched specific tires for each vehicle. The original equipment tires installed on the vehicle, when it was new, were designed to meet General Motors' Tire Performance Criteria Specification (TPC Spec) requirements. GM strongly recommends replacement tires with the same TPC Spec rating. This way, the vehicle will continue to have tires that are designed to give the same performance and vehi-

cle safety, during normal use, as the original tires.

In winter climates where snowfall may be significant, these performance tires will provide less traction than typical all-season tires. Winter tires are an available alternative that may greatly enhance winter driving.

If tires are replaced with non-TPC Spec tires, such as winter tires, in all cases, all four tires must be replaced. They must be the same size, load range, speed rating and construction type (radial and bias-belted tires) as the vehicle's original tires.

- Thanks to Richard Gratz,
Milford Proving Ground

Techline News — from page 1

the appropriate letter and you will be taken to that portion of the Pathing Table.

You can also search for a specific end string by clicking the binocular "find" icon, and typing in the exact phrase.

You'll also notice color coding for Powertrain (green), Chassis (blue) and Body (red), to further help you find what you're looking for.

For your convenience, there are buttons at the bottom of each page to take you to the next page or back to the

beginning. Simply position the pointing finger over the desired word and click.

Use the % pulldown menu or the + and - buttons to enlarge or reduce the size of the display as desired.

And finally, you can use the outstretched hand symbol to navigate within a page. Click and drag, and the symbol "grasps" the page, enabling you to move it in the desired direction.

- Thanks to Abra Quintero and
Mark Stesney

Corvette Service Notes

Brake Pads

For 2006, a new brake pad is introduced on the Z51 Corvettes for reduced operating noise. It is quieter than the pad used in 2005.

TIP: Use European specification brake pads for autocross competition. However, operating noise will be noticed with these pads.


Car Wash

The Z06 may not fit on some car washes due to the use of wider tires (rear tires are 13.6 inches, 325 mm, on 12-inch wheels). An information hang tag is included on the gearshift lever.

VIN

After the first 140 Corvette Z06s were built with a VIN Y designation for the engine, it was changed to VIN E. The LS7 engine is installed in all of the cars.

TIP: For these first 140 vehicles, it is necessary to use the letter E (instead of the Y on the plate) when specifying the vehicle in SI and on the Tech 2.



- Thanks to Brad Thacher

GM TechLink is a monthly magazine for all GM retail technicians and service consultants providing timely information to help increase knowledge about GM products and improve the performance of the service department.

Manager, Product Readiness:

R. M. (Bob) Savo
GM Service and Parts Operations
Bob.Savo@GM.com

Publisher & Editor:

Mark Stesney
GM Service and Parts Operations
Mark.Stesney@GM.com

Technical Editor:

Jim Horner
Jim_Horner@ADP.com
1-248-816-3641

Production Manager:

Marie Meredith

Desktop Publishing:

Greg Szpaichler, MediaWurks
Greg@MediaWurks.com

FAX number:

1-248-649-5465

Write to:

TechLink
PO Box 500
Troy, MI 48007-0500

GM TechLink on the Web:

<http://service.gm.com>

General Motors service tips are intended for use by professional technicians, not a "do-it-yourselfer." They are written to inform those technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions and know-how to do a job properly and safely. If a condition is described, do not assume that the bulletin applies to your vehicle or that your vehicle will have that condition. See a General Motors dealer servicing your brand of General Motors vehicle for information on whether your vehicle may benefit from the information.

Inclusion in this publication is not necessarily an endorsement of the individual or the company.

Copyright© 2005 General Motors Corporation
All rights reserved.

Windnoise Diagnosis Guide for SSR

Bulletin 05-08-58-003 has been released to help diagnose the following windnoise conditions in the 2003-05 Chevrolet SSR.

- Windnoise from the side and rear edge of the tonneau cover.
- Windnoise around the door glass.
- Windnoise from the weatherstrip joints.
- Leak in the rear corner between the front roof panel and seal.
- Windnoise from across the roof.
- Leak in the rear corner between the seal and the roof panel.
- Leak between the side rail weatherstrip retainer and the roof weatherstrip retainer.


Here are the GM parts that may be needed, depending on diagnostic results.

Part Number	Description
15257741	Seal, Roof FRT LH
15257742	Seal, Roof FRT RH
15257745	Seal, Roof RR PNL LH
15257746	Seal, Roof RR PNL RH

The following can be purchased from Kent Products by calling 1.800.654.6333.

Part Number	Description
P40320	Kent Automotive 3/8 x 50 inch Close Tolerance Foam

- Thanks to Dan Oden



Memory Seat Module

Owners of some 2000-05 Cadillac DeVilles may comment that the driver's seat will not return to its memory seat position when the RKE fob is used on an intermittent basis.

The condition will occur only after the vehicle has sat for more than 10 minutes on units equipped with memory seats AND massaging lumbar (RPO A45 or WA7). Typically, the seat will return if the memory recall button located on

the driver's door trim panel is used.

This condition has been identified as an inadvertent signal being sent by the seat massaging lumbar module to the seat memory module during RKE command. To correct this concern, rewire the massaging seat lumbar circuit. Refer to PIC 3554 for further details. A service bulletin is in development.

- Thanks to Bill Denton

Keyless Entry Key Fob Verification

You can use the information in SI document 1460262 to verify the keyless entry system key fob (passive).

System Operation Overview

It is not necessary to press a button on the passive fob to unlock the door. The fob simply has to be within one meter of an antenna in the vehicle.

In normal operation, when a door or compartment handle is operated, the remote control door lock receiver (RCDLR) in the vehicle transmits a "challenge" to the key fob.

If the challenge is met, the key fob

will respond to the RCDLR, allowing the door to be unlocked and opened.

Using the Tester

Place the key fob on the J 43241 test pad. Then approach the vehicle and attempt to open each door and rear compartment. The tester should beep during each entry attempt.

The beep indicates that the fob in question is the correct one for the vehicle being tested, and that the fob and vehicle are capable of communicating with each other.

- Thanks to Art Spong

Caster Measurement

This information applies to 2006 full-size C/K pickups and utilities and Hummer H2.

In the past, the caster specification on these vehicles was measured relative to the frame. So, when measuring the caster, you had to take an angle reading from the frame ahead of the rear wheels and add to or subtract from the caster readout on the alignment equipment. This was referred to as "corrected caster." If this was not done correctly, caster could be over- or under-adjusted.

Beginning with model year 2006, the published specification for caster for C/K and H2 trucks is relative to the ground. This means you can use the alignment equipment readout for caster directly, without compensation.

TIP: No changes have been made to the vehicle. The only difference is the way the caster specification is expressed.

TIP: This change does not apply to the Express and Savana vans, which continue to use "corrected caster" specifications.

- Thanks to Dan Stress

Oil Life System Reset Procedures – Cars

Many GM cars and trucks are equipped with an oil life system that determines when an oil change is required. After the oil has been changed, it's necessary to reset the system.

Procedures for resetting 2001 through 2006 passenger cars are published here.

TIP: You can find copies of charts for earlier models on the TechLink website on the Internet. Look for the February and March 2000 issues.

The information for this article is the same as you will find in the applicable owner or service manual. To find this information in 2001-04 SI service manuals:

- Select the vehicle
- Select category General Information
- Select category Maintenance and Lubrication
- Select category Maintenance and then GM Oil Life System-Resetting.

Beginning with 2005, this information will be found only in owner manuals. To find this information in SI owner manuals:

- Select the vehicle
- Select Owner Manual
- Select Service and Appearance Care
- Select Checking Under the Hood
- Select Description and Operation
- Select Engine Oil Life System

TIP: You may be able to use the Search function, using the words Oil Life.

2001-04 Seville

2001-05 DeVille

2006 DTS

1. Turn the ignition to ON but with the engine off.
2. Display the Oil Life message by pressing the Info button.
3. Press and hold the Reset button until the display shows 100% Engine Oil Life. This resets the oil life index.

2001-02 Eldorado

1. Turn the ignition to Run but with the engine off.
2. Display the OIL LIFE LEFT message by repeatedly pressing the SKIP INFO button.
3. Press the NO INFO RESET button until the display show 100% Engine Oil Life. This resets the oil life index.

2003-06 CTS

Base Audio System

1. Press the up or down arrow on the INFO button located to the right of the DIC display to access the DIC menu.
2. Once XXX% ENGINE OIL LIFE menu item is highlighted, press and hold the CLR button.
3. The percentage will return to 100, and the oil life indicator will be reset.
4. Repeat the steps if the percentage does not return to 100.

Navigation System

1. Turn the system on by pressing the PWR/VOL knob once. The PWR/VOL knob is located to the lower left of the DIC display.
2. Press the INFO button located to the left of the display to access the Vehicle Info menu.

3. Turn the TUNE/SEL knob located to the lower right of the display until Engine Oil Life is highlighted. Press the knob once to select it.
4. Once XXX% Engine Oil Life is displayed, press the multi-function button next to the Reset prompt in the upper right corner of the display.
5. The percentage will return to 100, and the oil life indicator will be reset.
6. Repeat the steps if the percentage does not return to 100.

2004-06 SRX

Base Audio System

Press the CLR button on the right of the DIC display to acknowledge the Change Engine Oil message. This will clear the message from the display and reset it. To reset the oil life indicator, use the following steps.

1. Press the up or down arrow on the INFO button located to the right of the DIC display to access the DIC menu.
2. Once XXX% ENGINE OIL LIFE menu item is highlighted, press and hold the CLR button. The percentage will return to 100, and the oil life indicator will be reset.
3. Turn the key to OFF.

If the Change Engine Oil message comes back when you start the vehicle, or the percentage does not return to 100, the engine oil life system has not reset. Repeat the procedure.

Navigation System

Press the display button to acknowledge the Change Engine Oil message. This will clear the message from the display and reset it. To reset the oil life indicator, use the following steps.

1. Turn the ignition to ON with the engine running.
2. Turn the system on by pressing the PWR/VOL knob located to the lower left of the DIC display
3. Press and hold the vehicle information display button located in the upper right of the screen for 3 seconds to enter the vehicle information menu.
4. Use the scroll up or down display keys to select Engine Oil Life.
5. Press and hold the RESET button on the display. The percentage will return to 100, and the oil life indicator will be reset. Repeat the steps if the percentage does not return to 100.
6. Press the RETURN button on the display to return to the main page.
7. Turn the key OFF.

If the Change Engine Oil message comes back when you start the vehicle, the engine oil life system has not reset. Repeat the procedure.

2004-06 XLR

2005-06 STS

1. Press the up or down arrow to scroll the DIC to show OIL LIFE.
2. Once the XXX% ENGINE OIL LIFE menu item is highlighted, press and hold the RESET button until the percentage shows 100%. Repeat the steps if the percentage does not return to 100.
3. Turn the key to OFF.

If the Change Oil Now message comes back when you start the vehicle, the engine oil life system has not reset. Repeat the procedure.

2001-05 Impala

2002-05 Monte Carlo

Using the Radio

1. Turn the ignition to ACC or ON, with the radio off.
2. Press and hold the TUNE DISP button on the radio for at least 5 seconds until SETTINGS is displayed.
3. Press the SEEK PTYPE up or down arrow to scroll through the main menu.
4. Scroll until OIL LIFE appears on the display.
5. Press the 1 PREV or 2 NEXT button to enter the submenu. RESET will be displayed.
6. Press the TUNE DISP button to reset. A chime will be heard to verify the new setting and DONE will be displayed for one second.
7. Once the message has been reset, scroll until EXIT appears on the display.
8. Press the TUNE DISP button to exit programming. A chime will be heard to verify the exit.

Using the Accelerator Pedal

1. Turn the ignition to ON, with the engine off.
2. Fully press and release the accelerator pedal 3 times within 5 seconds.
3. If the CHANGE ENGINE OIL message flashes, the system is reset. However, if it stays on, it did not reset. You'll need to repeat the procedure.

2006 Impala

2006 Monte Carlo

1. Turn the ignition to ON, with the engine off.
2. Fully press and release the accelerator pedal 3 times within 5 seconds.
3. If the CHANGE ENGINE OIL message flashes, the system is reset. However, if it stays on, it did not reset. You'll need to repeat the procedure.

2001-02 Intrigue

2001-03 Grand Prix w/o Trip Computer

2001-04 Century and Regal w/o DIC

2005 Century

1. Turn the ignition to RUN, with the engine off.
2. Fully press and release the accelerator pedal slowly 3 times within 5 seconds.
3. If the CHANGE OIL SOON light flashes, the system is resetting.
4. Turn the key to OFF after the light has finished flashing, and then start the vehicle.
5. If the CHANGE OIL SOON light comes back on, the engine oil life system did not reset. Repeat the procedure.

2001-04 Regal with DIC

1. Turn the ignition to RUN, with the engine off.
2. Fully press and release the accelerator pedal slowly 3 times within 5 seconds.
3. If the CHANGE OIL SOON light flashes, the system is resetting.
4. Turn the key to OFF after the light has finished flashing, and then start the vehicle.
5. To reset the DIC put the oil life display on the DIC.

6. Press the DIC RESET button for five seconds.
7. If the CHANGE OIL SOON light comes back on, the engine oil life system did not reset. Repeat the procedure.

2001-03 Grand Prix with Trip Computer

1. Press the MODE button until the light appears lit next to OIL LIFE.
2. Press and hold the RESET button for three seconds. The oil life percentage should change to 100%.

2004-06 Grand Prix

2005-06 Allure and LaCrosse with DIC

1. Press the options button on the DIC until ENGINE OIL MONITOR appears on the DIC screen.
2. Press the set/reset button to reset the system.

The next screen indicates that the engine oil monitor has been reset.

If the vehicle is equipped with the trip computer DIC, when the gage button is pressed and the OIL LIFE REMAINING mode appears, it should read 100 % OIL LIFE REMAINING.

3. Turn the key OFF.

If the Change Oil Soon message comes back when you start the vehicle, the engine oil life system has not reset. Repeat the procedure.

2005-06 Allure and LaCrosse w/o DIC

1. Turn the ignition to RUN, with the engine off.
2. Fully press and release the accelerator pedal slowly 3 times within 5 seconds.
3. Turn the ignition to OFF then start the engine.
5. If the light or message comes back on, the engine oil life system did not reset. Repeat the procedure.

2004-06 GTO

1. Turn the ignition to RUN, with the engine off.
2. Fully press and release the accelerator pedal slowly 2 times within 5 seconds.
3. Turn the ignition to LOCK.
4. Start the engine.
5. If the CHANGE OIL light comes back on, the engine oil life system did not reset. Repeat the procedure.

2001-03 Aurora

1. With the ignition on, press the SELECT right arrow button on the DIC to OIL so the OIL LIFE percentage is displayed.
2. Press RESET and hold for five seconds. OIL LIFE XXX% will appear and then when the button is released OIL LIFE 100% will be displayed.

2001-05 Bonneville

1. Display OIL LIFE on the DIC.
2. Press and hold the RESET button for more than five seconds. The oil life will change to 100%.

2001-05 LeSabre

2001-05 Park Avenue

1. Display OIL LIFE INDEX on the DIC.
2. Press and hold the RESET button on the DIC for more than five seconds. The oil life will change to 100%.

2006 Lucerne

1. Display OIL LIFE REMAINING on the DIC.
2. Press and hold the SET/RESET button on the DIC for more than five seconds. The oil life will change to 100%.

2001-06 Corvette

1. Turn the ignition to ON, with the engine off.
2. Press the TRIP button so the OIL LIFE percentage is displayed.
3. Press RESET and hold for two seconds. OIL LIFE REMAIN 100% will appear.

2001-02 Camaro

2001-02 Firebird

1. Turn the ignition to RUN but with the engine off.
2. Push the Trip/Oil Reset button located on the instrument panel for 12 seconds. The Oil Change light will start to flash to confirm that the system is reset. The reset is completed when the Oil Change light goes out.



2001-03 Grand Am

2001-03 Alero

1. Turn the ignition to ON.
2. Push the RESET button located in the driver's side instrument panel fuse block. The CHANGE OIL light will start to flash.
3. Press and hold the RESET button again. The reset is complete when you hear the chimes sound and the CHANGE OIL light goes out.

2004-05 Grand Am

2004 Alero

1. Turn the ignition to RUN, with the engine off.
2. Fully press and release the accelerator pedal slowly 3 times within 5 seconds.
3. The reset is complete when you hear the chimes and the Change Oil light goes out. If the light stays on and no chime is heard repeat the reset procedure.
4. Turn the key to OFF.
5. Start the engine. If the CHANGE OIL SOON light comes back on, the engine oil life system did not reset. Repeat the procedure.

2005-06 Cobalt

2005-06 Pursuit

2006 Solstice

1. Turn the ignition to RUN, with the engine off.
2. Press the information and reset buttons on the

DIC at the same time to enter the personalization menu.

3. Press the information button to scroll through the available personalization menu modes until the DIC display shows OIL LIFE RESET.
4. Press and hold the reset button until the DIC shows ACKNOWLEDGED. This will tell you the system has been reset display message will appear for 3 seconds or until the next button is pressed.
5. Turn the key to LOCK.
6. Start the engine. If the CHANGE OIL SOON message comes back on, the engine oil life system did not reset. Repeat the procedure.

2005-06 G6

1. With the CHANGE OIL SOON message displayed, press any of the three DIC buttons to clear the CHANGE OIL SOON message.
2. Display OIL LIFE RESET on the DIC.
3. Press and hold the ENTER button for at least one second. An ACKNOWLEDGED message will appear for three seconds or until the next button is pressed. This tells you the system has been reset
4. Turn the key to OFF.
5. Start the engine. If the CHANGE OIL SOON message comes back on, the engine oil life system did not reset. Repeat the procedure.

2004-06 Malibu

1. Display OIL LIFE RESET on the DIC.
2. Press and hold the ENTER button for at least one second. An ACKNOWLEDGED display message will appear for 3 seconds or until the next button is pressed. This will tell you the system has been reset.
3. Turn the key OFF.

If the Change Oil Soon message comes back when you start the vehicle, the engine oil life system has not reset. Repeat the procedure.

2002-05 Saturn L

1. Turn the ignition to RUN, with the engine off.
2. Fully press and release the accelerator pedal 3 times within 5 seconds.
3. If the CHANGE OIL SOON light is flashing, the system is reset. The light will flash for up to 30 seconds or until the ignition is turned off.
4. If the light comes on again and stays on for 30 seconds at the next ignition cycle, it did not reset. Reset the system again.

2003-06 Saturn Ion

1. Press and release the trip/reset button until the OIL LIFE message is displayed.
2. Press and hold the trip/reset button until a chime sounds 5 times and RESET is displayed in the message center. When the system is reset, the odometer will again be displayed in the message center.
3. Turn the key OFF.

If the CHG OIL message comes back on when you start the vehicle, the system has not reset. Repeat the procedure.

- Thanks to Jerry Garfield

Wiring Harness Repair Issues

When a replacement harness is ordered from GMSPo, a determination is made by the Product Quality Center (PQC) whether it is a Body or I/P Harness. If the harness is on order restriction, the dealer will be directed to repair the harness if possible, instead of replacing it. Most damage to a harness can be repaired, often quicker than a replacement harness can be shipped.

This is particularly true if the harness is for a vehicle no longer under warranty. GMSPo now stocks few harnesses for these vehicles, and likely will carry even fewer in the future. In these cases, a replacement harness must be hand-built, which results in a very long wait time.

TIP: Some vehicles are outside this harness restriction. These include the International Joint Venture Platforms (IJVP) e.g., Pontiac Vibe, Tracker, etc., and the MD Trucks (GMT 560).

For vehicles still in production, the harness may be available through the Ship Direct Process.

Ship Direct Process

GM has several wiring harness suppliers. To qualify for the Ship Direct Process, the supplier must agree to stock every harness that is in current production, and must be prepared to send the harness directly to a dealer if one is ordered.

If PQC determines that a new harness is necessary, and if the wiring supplier of the needed harness participates in the Ship Direct Process, a new harness is shipped the next day.

Once there is a change to a production harness such that the new part cannot service the previous part number, then GMSPo stocks the previous part and the

new number becomes the new Ship Direct part. This will continue until the vehicle is no longer in production.

Availability of Repair Parts

It is always best to repair a harness rather than replace a harness. GMSPo offers everything needed to make a wiring repair – including tape, wire, clips, clamps and conduit.

Connector assemblies can be purchased several ways. Some connectors consist of only the connector body. In other cases, several loose parts are needed to make up a complete connector (TPA, CPA, empty cavity plugs, wire cover, etc.). If so, the connector will come as a Connector Kit, available from GMSPo. Simply order the connector in question and you will get the necessary part(s).

TIP: There are also pigtails available for any connection system with eight cavities or less.

Every GM dealer has a J-38125 Terminal Repair Kit which will soon be updated with four new trays of terminals. If this kit is kept properly maintained and organized, it will provide replacements for nearly any terminal now in use in GM vehicles. In fact, the kit has replacement terminals and repair tools for every GM platform from 1956 to the present.


Other Issues

If the vehicle in question is in a body shop for collision repairs rather than warranty repairs, the harness is still going to be a restricted sale. So, repairing the harness rather than replacing it may be the most appropriate action. This should be addressed on a case by case basis.


If an independent repair shop wishes to order a harness, they should understand



Damaged connector and terminals can be replaced



Cut wires can be spliced



SIR connector can be replaced with pigtail

this harness availability situation. They can repair the harness in the same manner that a dealer can; the parts are available. For older vehicles, they must be prepared to wait for a replacement harness.

- Thanks to John Roberts

New Model Features on the Web

GM STC is enhancing the training program with an effective new Web tool (US only). To better serve the GM technician audience and to ensure new model technical information is available just-in-time, starting March 2005 the majority of New Model Features (NMF) information is being delivered on the GM Training Website.

In the past, New Model Feature IDL seminars were used to deliver this information, either covering a whole division or focusing on a few vehicles. While IDL seminars and Service Know-How videos may still be used occasionally to introduce a new vehicle, the majority of vehicles will be showcased in their own web based module.

This new delivery method allows the technicians to review modules on specific vehicles highlighting those items that are new or updated for the model year. The

information is available on-demand any time, day or night, reducing time away from the service bay. The enhancement further satisfies service technicians' need for on-demand knowledge resources.

With the NMF Web tool, training information will consist of media files that are easily accessible from the GM Training Website. From the Menu, click Service Know-How/TECHAssist.

The training modules are created for individual vehicles using text, 2D & 3D animation, photos and video. The NMF modules will coincide with new vehicle release dates throughout the year.

Modules are not directly associated with any GM STC certification. However, credit is applied to the technician training record upon successful completion of the module. NMF modules are intended to be informational in nature, providing timely data

to help improve performance on the job.

How to Access NMF Modules

An easy-to-use interface is available for users to find the new model content they need. To begin, do the following:

1. Log on to the GM Training Website (www.gmtraining.com).
2. From the Menu, click Service Know-How/TECHAssist.
3. Under the table of contents, select New Model Features.
4. Select the division of the vehicle you wish to view
5. Click the vehicle you wish to view. This will open the catalog page.
6. Click Launch Course

If you have any questions, please contact the GM Training Help Desk at 888.748.2687, or visit the GM Training Website (www.gmtraining.com).

- Thanks to Susan Fritschi

Front Drive Axle Lubricant

This lubrication information applies to 1999-2005 light duty trucks with 4-wheel or all-wheel drive and with separate front drive axle carriers.

IMPORTANT: Front drive axle carriers do not require periodic lubricant replacement.
- Thanks to Jerry Garfield

Axle Size	Years	SAE 80W-90 Axle Lubricant. p/n 1052271 or 89021671 (U.S.) p/n 10950849 or 89021672 (Canada)	SAE 75W-90 Synthetic Axle Lubricant meeting GM Specification 9986115 p/n 12378261 or 89021667 (U.S.) p/n 10953455 or 89021678 (Canada)
7.25 inch	1999-2001	Use	Can use but not required
7.25 inch	2002-2005	-	Use
8.25 inch with selectable 4WD	1999 - 2005	Use	Can use but not required
8.25 inch with AWD	1999 - 2005	-	Use
9.25 inch	1999-2001	Use	Can use but not required
9.25 inch	2002-2005	-	Use

Tie Rod Specifications Revised

Bulletin 05-02-32-003 is being issued to revise the outer tie rod end nut tightening specification and to include the tie rod end jam nut tightening specification in the Power Steering sub-section of the Service Manual for model years 1998-2005. It affects Buick Regal and Century, Chevrolet Monte Carlo and Impala, Oldsmobile Intrigue and Pontiac Grand Prix.

Application	Specification	
	Metric	English
Outer Tie Rod End Nut*	30 Nm + 120°	22 lb ft + 120°
Tie Rod End Jam Nut	70 Nm	52 lb ft

* Visually inspect to ensure that 2 1/2 to 4 1/2 threads are visible past the nylon washer.

- Thanks to Pete Kalaj

TAC Tips

Headlamps On in Daytime

Owners of some 2005 Cadillac STSs may comment that the low beam headlamps (not DRLs) are on during daylight conditions.

Inspect the windshield wiper switch position. If the windshield wiper switch is in any ON position, the IPM will command on the headlamps. This is a normal condition.

TIP: Vehicles equipped with Rainsense windshield wipers may have the wiper switch on with no activation of the wipers.

- Thanks to Jim Will

Battery Draw

When parking a 2004-05 Chevrolet Colorado or GMC Canyon Pick Up with the key left in the ignition, a battery draw may occur. This will be noticed only when the door is not completely closed to the primary latch position. If the door is closed only to the secondary latched position, the chime will sound continuously and the radio will not time out, resulting in a battery draw or dead battery. This is a normal operating characteristic.

When leaving the key in the ignition, it is important to be sure that all doors are closed completely to the primary latch position. Making the customer aware of this concern will lead to a resolution.

- Thanks to Dino Poulos

Intermittent Dome Lamp Operation

On some Hummer H3s, the warning chime may sound intermittently, the dome lamp may come on and/or the door locks may cycle. This typically occurs when going over bumps or accelerating. The cause may be the adjustment of the swing gate closing switch.

Using the Tech 2, monitor the BCM input data for the "Passenger Door Ajar Sw."

TIP: This input is for all of the passenger doors. It may be necessary to disconnect the swing gate ajar switch to verify it is the source of the concern.

If the concern is isolated to the swing gate ajar switch, apply a sticky backed rubber or plastic patch approximately



3 mm thick to the swing gate inner panel where the switch contacts the door.

- Thanks to Ron Erman

Interior Turning Pink

Owners of some 2004-06 Cadillac XLRs may comment that the interior of the vehicle is turning pink. The concern may be seen on door panels, the driver's knee bolster and passenger's glove box. The concern is mostly apparent on vehicles equipped with the Shale interior (RPO 15I). The condition is linked to vehicles that are stored in the winter months in a warehouse that uses propane fork lift (hi-lo) vehicles. The dye of the interior reacts to high concentrations of combustion by-products and turns to a pink tint.

Most of the pink discoloration can be removed by using a 50-50 mixture of

isopropyl alcohol and water. Exposure to natural sunlight for 2-3 hours will completely remove the pink coloration.

- Thanks to Paul Radzwilowicz





Car Issues – Fix It Right the First Time (new issues in **bold**)

Model Year(s)	Vehicle Line(s) / Condition	Do This	Don't Do This	Reference Information / Bulletin
2004-2005	Grand Prix, LaCrosse – Blower Motor Inoperative or Intermittent, Blower Speed May Drop or Blower Continues to Run After Key Off	Install 330MFD capacitor between LPM circuit and ground.	Don't replace LPM, blower motor or HVAC control head.	05-01-39-001A
2002-2005	Buick LeSabre – Front Door Window Binds/Inoperative/Moves Slowly	Adjust glass.	Don't replace window regulator.	05-08-64-011
2002-2007	Cavalier, Sunfire, Grand Am, Classic – Vehicle Hesitates, No Start, Lack of Power, Low Fuel Pressure	Replace fuel pump strainer.	Don't replace fuel pump module.	05-06-04-026A
2001-2003	Aztek, Rendezvous – Window Regulators Separate from Window Motors	Use window regulator clips and procedure in 05-08-64-008 instead of replacing complete window regulator assemblies.	Don't replace window regulator assemblies that are serviceable and only have broken clips.	03-08-64-015
1999-2004	All Cars and Trucks – Brake Warranty, Service and Procedures	Issue One: Refinish brake rotor. Issue Two: Measure for LRO	Issue One: Don't replace the brake rotors. Issue Two: Don't measure for LRO	00-05-22-002D
2002-2005	Cars and Trucks – Multiple Driveability Symptoms/Clogged Fuel Injectors	Clean fuel injectors as described in Bulletin.	Don't replace fuel injectors.	03-06-04-030A



Truck Issues – Fix It Right the First Time (new issues in **bold**)

Model Year(s)	Vehicle Line(s) / Condition	Do This	Don't Do This	Reference Information / Bulletin
2005	SSR, Colorado/Canyon, TrailBlazer, Envoy, Rainier – CD Issues	Load new radio software calibration.	Don't replace or exchange radio.	04-08-44-021A
2003-2005	Full Size Pickup and Utilities, H2 – Rear Seat Audio and/or Rear HVAC Controls Inoperative	Replace RSA.	Don't replace console.	03-08-44-018A
2001-2005	Chevrolet/GMC 36 Series Cab/Chassis – DTC P1172 or P2636, Fuel Gauge Reads Empty, SES Light On	Modify fuel tank balance line.	Don't replace fuel tank unit, PCM or fuel transfer pump.	05-06-04-008
2002-2005	Escalade, Yukon – Stains on Rear Bumper Step Pad	Apply Armor-Dillo to rear step pad.	Don't replace rear step pad.	03-08-43-002A
2000-2003	Tahoe, Suburban, Yukon, Yukon XL – DTC P0446 Set, SES Illuminated	Replace EVAP vent solenoid.	Don't replace EVAP canister.	04-06-04-055
2004-2005	Midsize and Fullsize Pickups and Utilities – CD Issues	Load new software calibration.	Don't exchange or replace radio.	04-08-44-020A
2002-2005	Tahoe, Suburban, Yukon, Escalade, Avalanche, H2 – Exhaust Pop/Ping Noise	Replace heat shield.	Don't replace exhaust system.	03-06-05-008B
2004-2005	All Cars and Trucks – State-of-Charge Upon Delivery of New Vehicle	Check battery's state-of-charge per revised PDI procedure using J-42000 or J-42000-EU.	Don't remove and replace battery.	02-06-03-009A
2002-2004	Silverado, Suburban, Tahoe, Sierra, Yukon/XL, Escalade EXT – Rough Idle, Misfire, MIL DTC P0300	Measure intake manifold for warpage across two runner ports only. Replace upper manifold gasket with teal-green gasket.	Don't measure intake manifold for warpage across all four intake runner ports. Don't replace upper intake manifold gasket with orange-colored gaskets.	05-06-04-029
2001-2003	Fullsize Pickups – Injector Replacement for High Flow Rates	Use Corporate Bulletin Number 04-06-04-007A for injectors with high fuel return rates. Use Special Policy 04039 for all 01-02 vehicles.	Don't replace 8 injectors for any complaint other than high fuel return rates. All other injector failures are fix as failed.	Special Policy 04039

**Know-How
Broadcasts
for
October**

10290.09D Emerging Issues

New Model Features

October 6, 2005, 9:30 AM and 12:30 PM Eastern Time

For Web NMF courses, log on to the GM Training Website (www.gmtraining.com). Select Service Know-How from the menu, then choose New Model Features for a selection of courses.



– Thanks to Tracy Rozman